




寸法表

単位：mm

| 呼び径   |     | d   | H   | D1  | L   | l   | フ ラ ン ジ |         |    |    |                   |    |  |  |
|-------|-----|-----|-----|-----|-----|-----|---------|---------|----|----|-------------------|----|--|--|
|       |     |     |     |     |     |     | D       | ボ ル ト 穴 |    |    | ボルトの<br>ねじの<br>呼び | t  |  |  |
|       |     |     |     |     |     |     |         | C       | 数  | h  |                   |    |  |  |
| 1.1/2 | 40  | 40  | 210 | 140 | 140 | 44  | 140     | 105     | 4  | 19 | M16               | 18 |  |  |
| 2     | 50  | 50  | 250 | 140 | 146 | 57  | 155     | 120     | 4  | 19 | M16               | 18 |  |  |
| 2.1/2 | 65  | 65  | 285 | 160 | 159 | 72  | 175     | 140     | 4  | 19 | M16               | 18 |  |  |
| 3     | 80  | 80  | 350 | 160 | 165 | 91  | 185     | 150     | 8  | 19 | M16               | 18 |  |  |
| 4     | 100 | 100 | 400 | 180 | 171 | 110 | 210     | 175     | 8  | 19 | M16               | 20 |  |  |
| 5     | 125 | 125 | 460 | 225 | 190 | 133 | 250     | 210     | 8  | 23 | M20               | 22 |  |  |
| 6     | 150 | 150 | 515 | 225 | 210 | 160 | 280     | 240     | 8  | 23 | M20               | 22 |  |  |
| 8     | 200 | 200 | 635 | 300 | 241 | 211 | 330     | 290     | 12 | 23 | M20               | 24 |  |  |
| 10    | 250 | 250 | 760 | 350 | 273 | 263 | 400     | 355     | 12 | 25 | M22               | 26 |  |  |
| 12    | 300 | 300 | 870 | 350 | 305 | 314 | 445     | 400     | 16 | 25 | M22               | 28 |  |  |

# KITZ

[illegible]